



- CITIZEN INPUT LEGEND:**
- SHED / STORAGE FLOODING
  - CRAWLSPACE FLOODING
  - LIVING SPACE FLOODING
  - FLOODING OCCURS MULTIPLE TIMES PER YEAR
  - EXISTING WATERSHED BOUNDARY
  - EXISTING STORM SYSTEM
  - STREET FLOODING
  - NO PROBLEM REPORTED
  - FLOODING OF HVAC PAD
  - EROSION PROBLEM REPORTED
  - "311" REQUEST CLOSED
  - "311" REQUEST (PRIORITY C)
  - "311" REQUEST (PRIORITY B)
  - "311" REQUEST (PRIORITY A)

- MODEL RESULTS**
- FINISHED FLOOR FLOODING
  - CRAWL SPACE FLOODING
  - LAG, GARAGE, HVAC, OR STORAGE BLDG FLOODING
  - STREET FLOODING
  - DEFICIENT STORMWATER PIPES

**HINSDALE - TINKERBELL  
STORM DRAINAGE IMPROVEMENTS**  
**FIGURE EC-8**  
**CITIZEN REQUEST, QUESTIONNAIRES,  
AND MODELED RESULTS**

200' 0 200' 200' 400'  
 HORIZONTAL SCALE: 1" = 200'  
**DATE: 3/28/2013**

PREPARED FOR:  
  
**Charlotte-Mecklenburg  
STORM  
WATER  
Services**

PREPARED BY:  
**Armstrong Glen, P.C.**  
 9731-L Southern Pine Boulevard  
 P.O. Box 7326  
 Charlotte, NC 28241  
 Phone: 704-529-0345  
 Fax: 704-529-0493  
 License #: C-1856

**CHARLOTTE**