

PDF pg	#	Number or Reference Label	Version Date	Original Number or Reference Label (date unknown and 2016)	Description
					Sewer Rehab
	1	16.1	04/2024	A	REHABILITATION OF EXISTING MANHOLES
	2	16.2	04/2024	B	TYPICAL POINT REPAIR
	3	16.3	04/2024	C	REHABILITATION OF MANHOLE WALLS AND TOP SECTION
	4	16.4	04/2024	D	REHABILITATION OF MANHOLE WALLS AND TOP SECTION (WITH CONE SECTION)
	5	16.5	04/2024	E	NEW PIPE CONNECTION AT EXISTING MANHOLE
	6	16.6	04/2024	F	SERVICE LATERAL REPLACEMENT
	7	16.7	04/2024	G	CLEANOUT REPLACEMENT
	8	16.8	04/2024	H	REHABILITATION OF MANHOLE FRAME AND COVER
	9	16.9	04/2024	J	LINER CONNECTION AT MANHOLE
	10	16.10	04/2024	L	HDPE PIPE CONNECTION AT MANHOLE FOR PIPE BURSTING
	11	16.11	04/2024	(HDPE DETAILS) HD22	4-INCH TO 6-INCH SEWER CLEANOUT AND LATERAL ON HDPE PIPE BY PIPE BURSTING