Appendix 2

Photo 1: Reach 1 – Looking downstream.

Photo 2: Reach 1 –Left bank.

Title	Reach 1 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services

Project	
Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	

Date	**KHA Project Number**	**Site Photo Page**
5/23/12	015016139	1

Photo 3: Reach 2 – Looking downstream.

Photo 4: Reach 2 – Right bank.

Title	Reach 2 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services	**Project**	Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	
	Date 5/23/12	**KHA Project Number** 015016139	**Site Photo Page** 2

Photo 5: Reach 3 – looking upstream

Photo 6: Reach 3 – Right bank

Title	Reach 3 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services

Project	
Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	

Date	**KHA Project Number**	**Site Photo Page**
5/23/12	015016139	3

Photo 7: Reach 4 – Looking downstream

Photo 8: Reach 4 – Left bank.

Title	Reach 4 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services

Project	Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	
Date	**KHA Project Number**	**Site Photo Page**
5/23/12	015016139	4

Photo 9: Reach 5 – Unstable degraded area looking upstream



Photo 10: Reach 5 – Preservation area (Potential Reference)

Title	Reach 5 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services

Project	Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	
Date	**KHA Project Number**	**Site Photo Page**
5/23/12	015016139	5

Photo 11: Reach 6 – Unstable degraded area looking downstream

Photo 12: Reach 7 – Unstable degraded area looking downstream

Title	Reach 6 & 7 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services

Project	Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	
Date	**KHA Project Number**	**Site Photo Page**
5/23/12	015016139	6

Photo 13: Reach 8 – Unstable degraded area looking downstream

Photo 14: Reach 9 – Unstable degraded area looking downstream

Title	Reach 8 & 9 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services

Project	Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	
Date	**KHA Project Number**	**Site Photo Page**
5/23/12	015016139	7

Photo 15: Reach 10 – Unstable degraded area looking downstream

Photo 16: Reach 11 – Unstable degraded area looking downstream

Title	Reach 10 & 11 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services

Project	Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	
Date	**KHA Project Number**	**Site Photo Page**
5/23/12	015016139	8

Photo 15: Reach 6 – Stable area above headcut.

Title	Reach 6 Photographs

Prepared For: Charlotte-Mecklenburg STORM WATER Services

Project	Reedy Creek Feasibility Study Charlotte, Mecklenburg County, North Carolina	
Date	**KHA Project Number**	**Site Photo Page**
5/23/12	015016139	9