



August 2016



Construction continues on Brentwood Place Phase I. Work within the railroad right-of-way has begun. The concrete endwalls have been completed upstream and downstream of the railroad tracks. The contractor is in the process of installing the first of two 54" steel pipes beneath the railroad tracks. To avoid disruption to railroad operations, the contractor is tunneling under the railroad tracks to install the 54" steel pipes.

Phase II Construction is complete. A final walk through was performed and City Construction staff are now working with the contractor to complete the outstanding punch list items.

Photos
(Left) *Railroad tunnel preparation*
(Center) *Contractor prepares to tunnel under railroad*
(Right) *Tree removal at the downstream end near railroad*

Brentwood Place Storm Drainage Improvement Project



Engineering & Property Management
Storm Water Services Division
600 East Fourth Street
Charlotte, North Carolina 28202

Photo: *Contractor prepares for tunnel operation under the railroad*

Brentwood Place Storm Drainage Improvement Project

Construction is ongoing for Phase I and complete for Phase II of Brentwood Place Storm Drainage Improvement Project. Throughout construction, efforts will be made to minimize disruption to nearby property owners. A construction inspector will be on site daily to address any questions or concerns.

For questions, please contact one of the following project team members:
On-site Construction Inspector:
Matthew Hayes: 704-678-6092
Email: Matthew.Hayes@charlottenc.gov
Construction Supervisor:
Scott Ackerman: 980-721-3653
E-mail: sackerman@charlottenc.gov
Project Manager:
Tom Purvis: 704-336-3660
Email: tpurvis@charlottenc.gov

For more information: stormwater.charmeck.org