


Landscape Management Emergency Response Event Summary
22 May 2020 Storm and Tropical Storm Bertha
6/2/2020 4:00 PM

Data compiled for storm damage from the 22 May 2020 Storm and Tropical Storm Bertha was collected from 4 pm on 22 May through 1 June at 3 pm. Updates will continue until all storm damage requests have been completed and all impacted streets are cleared of debris.

Event Summary - 22 May 2020 Storm and Tropical Storm Bertha	
377	Total Storm Damage Tree Debris Service Requests *
3	Roads completely blocked
0	Major Streets Completely Blocked**
1	Secondary Streets Completely Blocked** (work in progress by contractors)
Major Streets Completely Blocked	
Notes	
Landscape Management's main objective during storm response is to clear roads of debris to provide at a minimum single lane access for first responder vehicles along major thoroughfares and at priority sites (hospitals & police/fire/medic stations). Next level objectives include clearing single-lane access on secondary roads and all-lane access for non-emergency vehicles (driveways, sidewalks, bike lanes, etc.). Clearing of debris is pushing downed trees out of the way, hauling off debris will typically take place at a later date.	
National safety standards prevent City crews from working in close proximity to downed utility lines of any kind. Debris clearing is often delayed due to coordination with utility companies.	
* Tracking for TS Bertha began at 12:00 am 27 May; Landscape Management received 84 requests beginning on 27 May	
** Quantity known at this time	



Landscape Management Storm Response Heat Map
Storm 5/22/2020 & Tropical Storm Bertha

